LOGAIR.AI™ · AVIATION AIRWORTHINESS DIRECTIVES

LogAir.ai™ AD Status Report — N155JA

Generated 10/1/2026 10:10 PM · NotebookLM notebook e614ce40-29ee-4d94-9d25-3df95a1b8c4c

PART 1: AIRCRAFT & COMPONENTS

Registration	N155JA	**Manufacturer**	Textron Aviation
Model	95-B55	**Serial Number**	TC-1993
Year	1976	**Total Time**	4594.2 Hours
Left Engine	Continental Motors IO-470-L · S/N 468246-CS	**Right Engine**	Continental Motors IO-470-L · S/N 297559-R
Left Propeller	McCauley 3AF32C504-C / 82NEA-4 · S/N 080816	**Right Propeller**	McCauley 3AF32C504-C / 82NEA-4 · S/N 080817

SUMMARY

SECTION	NO EVIDENCE	RECURRING	COMPLIED	N/A	UNCLEAR	NOT EVALUATED	NOT CHECKED	TOTAL
Airframe	2	2	8	13	–	–	–	**25**
Left Engine — Continental Motors IO-470-L · S/N 468246-CS	2	–	5	13	–	–	–	**20**
Right Engine — Continental Motors IO-470-L · S/N 297559-R	1	–	6	13	–	–	–	**20**
Left Propeller — McCauley 3AF32C504-C / 82NEA-4 · S/N 080816	–	–	–	3	–	–	–	**3**
Right Propeller — McCauley 3AF32C504-C / 82NEA-4 · S/N 080817	–	–	–	3	–	–	–	**3**
Appliances	23	3	6	311	–	–	–	**343**
Logbook ADs Not in FAA DRS	–	–	–	–	–	–	–	**0**

PART 2: AD COMPLIANCE

Airframe

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
No Evidence Found						
68-26-06 02/05/1974	Placard Installation					
2001-23-10 12/13/2001	Flap Flex Shaft Assemblies			No		
Recurring						
90-08-14 05/07/1990	Wing Spar Structure	10/25/2023, 4426.0 Hobbs	Complied with by dye penetrant inspection of wing forward spar carry-through structure in accordance with SB 2269	Yes	4926.0 Hobbs	A&P 2733194 IA Kurt Moffat
2007-08-08 05/25/2007	Uplock roller	12/15/2025, 4589.5	Lubricated uplock mechanism	Yes	4689.5 ACTT	A&P 2733194 IA Kurt Moffat

Airframe (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Complied With						
84-09-01 05/25/1984	Window Emergency Egress Provision	01/02/1986, 1468.0 Hobbs	Reworked emergency exit window release pin and placard	No		CRS 4308 D. Willson
88-21-02 10/31/1988	Seat Tracks	03/09/1989, 1792.4 Hobbs	Complied with per SB 2010R1 by visual inspection and installation of washers on seat frame assemblies	No		CRS 3786 William Ingersoll
91-17-01 11/25/1991	Elevator Trim Tab Actuators	02/06/1992, 2130.3 Hobbs	Complied with per SB 2399 by color coding left-hand and right-hand elevator trim tab actuators	No		CRS CGHR812C Tom James
97-14-15 09/02/1997	Cabin Side Door And Utility Door Handle	03/04/1998, 2611.6 Hobbs	Inspected and tested cabin door handle for proper latching in accordance with SB 2693	No		CRS CGHR812C Curt E. Voves
99-05-13 R1 WD 07/05/2000	Withdrawal of AD 99-05-13	04/13/2000, 2772.4	Installed fuel selector-warning placard, P/N 36-920059-1, in accordance with SB 2670 R1	No		CRS CGHR812C, Jason D. Staver
2000-18-02 09/22/2000 (found on second check)	Elevator Skin Assemblies	07/05/2000, 2787.9	Installed overhauled left elevator P/N 96-610005-655 S/N BAI-1790-1 IAW SB 27-3390 Rev 1	No		CRS PRIR248H Priester Aviation Services Inc
2008-13-17 08/06/2008	Circuit breaker toggle switches	12/15/2025, 4589.5	Replaced affected circuit breaker toggle switches with approved improved switches P/N 35-380132-61 through -113 series	No		A&P 2733194 IA Kurt Moffat
2009-25-01 01/08/2010	Shoulder harnessess	08/06/2010, 3207.0	Inspected shoulder harness installation and verified correct washer installation	No		CRS NF2R029L Donald K. Morgan
Not Applicable (N/A)						
67-29-01	Rudder Spar Web		Aircraft serial number TC-1993 is not in affected serial number range (TC-371, TC-502 through TC-1042)	No		
71-24-10 08/01/1973	Security of Control Wheel		Serial number TC-1993 is not in affected range (TC-1021 through TC-1397, or TC-371 and TC-502 through TC-1020)			
72-01-02 01/05/1972	Oil Drain Tubes		Serial number TC-1993 is not in affected range (TC-371, TC-520 through TC-1409)			
72-11-02 05/20/1972	Engine Fuel Interruption		Serial number TC-1993 is not in affected range (TC-1 through TC-1425)			
73-14-03 07/06/1973	Landing Gear Shock Strut Piston		Serial number TC-1993 is not in affected range (TC-1484 through TC-1544)			
73-26-08 12/26/1973	Roll and Pitch Servo Clamps		Serial number TC-1993 is not in affected range (TC-1 through TC-1573)			

Airframe (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Not Applicable (N/A) (continued)						
74-03-02 02/05/1974	Landing Gear Shock Strut Piston		Serial number TC-1993 not in affected serial number range (TC-1552 through TC-1607)	No		
74-24-03 11/22/1974	Strobe Light System		Model 95-B55 S/N TC-1993 not within affected range TC-1526 thru TC-1811	No		
75-16-10 08/06/1975	Elevator Trim Tab		S/N TC-1993 exceeds applicable serial range max TC-1775	No		
76-22-02 06/02/1977	'Y' Type Shoulder Harness		S/N TC-1993 is above affected range TC-1653 through TC-1946	No		
77-02-04 03/03/1977	Wing Tip Strobe Lights		S/N TC-1993 is beyond affected range TC-1299 through TC-1525	No		
79-01-01 01/08/1979 (found on second check)	Screws in Control System	10/3/79, 518	N/A - Has x head screws	No		A. Bajc A&P 479768745
89-05-02 03/24/1989	Elevator Control Fittings		Aircraft serial number TC-1993 is outside the applicable serial number range (TC-1 through TC-1287 for Model 95-B55)	No		

Left Engine — Continental Motors IO-470-L · S/N 468246-CS

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
No Evidence Found						
2009-19-07 10/07/2009	EQ3 cylinders					
2010-11-04 06/16/2010 **(L and R differ — review)**	Hydraulic lifters					
Complied With						
70-14-07 11/22/1974	Fuel Injection Pump	07/16/2009, ACTT 2754.5	Complied with at overhaul per TCM SB M70-10 R1 (new plug installed)	No		CRS MW2R020L G&N Aircraft Inc.
88-03-06 04/15/1988 (overhaul statement)	Oil Filter	07/16/2009, 2754.5	Overhaul entry: "All applicable Airworthiness Directives and Manufacturer's Service Bulletins are in compliance as of the date of overhaul."			C.R.S. # MW2R020L / -
91-19-03 09/29/1991 (overhaul statement)	Oil Filter	07/16/2009, 2754.5	Overhaul entry: "All applicable Airworthiness Directives and Manufacturer's Service Bulletins are in compliance as of the date of overhaul."			C.R.S. # MW2R020L / -

Left Engine — Continental Motors IO-470-L · S/N 468246-CS (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Complied With (continued)						
93-08-17 08/23/1993 (overhaul statement)	Oil Pick-Up Tube	07/16/2009, 2754.5	Overhaul entry: "All applicable Airworthiness Directives and Manufacturer's Service Bulletins are in compliance as of the date of overhaul."			C.R.S. # MW2R020L / -
2023-17-04 10/26/2023	Reciprocating Engine Oil System	12/15/2025, ACTT 4589.5	Complied with per Stratus SB-001 Rev D (copper gasket installed on F&M oil filter adapter)	No		A&P 2733194 Kurt Moffat / IA 3873674 Michael A. Ondik
Not Applicable (N/A)						
72-20-02 10/02/1974	Cylinders	07/16/2009, 2754.5	Recorded in logbook as N/A by date of manufacture per SB M73-2	No		CRS MW2R020L G&N Aircraft Inc.
77-05-04 03/11/1977	Crankshaft		N/A by aircraft serial number (applies to Beech 95-B55 S/N TC-2003 through TC-2053; aircraft is S/N TC-1993)	No		
79-05-09 03/12/1979	Oil Pump Assembly Or Oil Pressure Relief Valve Screw And/Or Plunger		N/A by engine serial number (S/N 468246-CS is not in affected serial number range)	No		
93-10-02 08/12/1993	Missing Cylinder Valve Retainer Key	07/16/2009, 2754.5 ACTT	Recorded as N/A by date per SB M93-12 (engine accumulated 25 or more hours TIS prior to AD effective date)	No		CRS MW2R020L G&N Aircraft Inc
95-21-15 11/28/1995	Aviation Gasoline		Aircraft N155JA not listed in AD applicability (applies only to specific listed aircraft tail numbers)	No		
97-21-02 10/27/1997	Cylinders	07/16/2009, 2754.5 ACTT	Recorded as N/A by new cylinder kits installed at overhaul per CSB97-10A	No		CRS MW2R020L G&N Aircraft Inc
98-01-08	Exhaust Roller Rocker Arm	07/16/2009, 2754.5	N/A by P/N (PE92E rocker arms not installed)	No		CRS MW2R020L Dan Morgan
99-19-01 09/30/1999	No. 2 and No. 5 Crankshaft Inspections	07/16/2009, 2754.5	N/A by S/N (Not in affected serial number range per MSB 99-3C)	No		CRS MW2R020L Dan Morgan
2000-23-21 12/12/2000	Crankshaft	07/16/2009, 2754.5	Engine and crankshaft date of manufacture or overhaul outside affected range (April 1, 1998 to March 31, 2000); recorded as N/A by date per TCM SB 00-5D	No		CRS MW2R020L G&N Aircraft Inc.
2012-03-06 02/24/2012	Fuel servo diaphragm		Equipment not installed (engine equipped with Continental fuel injection system, not AFS fuel servo)	No		

Left Engine — Continental Motors IO-470-L · S/N 468246-CS (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Not Applicable (N/A) (continued)						
2022-16-03 08/15/2022	Engine (RECIPROCATING)		Equipment not installed (affected S-1200 series magneto serial numbers between F21EA057 and F21KA009R not installed)	No		
2023-02-12 02/17/2023	Engine Air Intake System		Equipment not installed (no affected SAP cylinder assembly or intake valve lot 19077 O installed on or after January 20, 2022)	No		
2023-05-16 03/15/2023	Reciprocating Engine Power Section	12/15/2025, ACTT 4589.5	Determined not applicable per logbook entry (crankshaft not in affected S/N or manufacture date range)	No		A&P 2733194 Kurt Moffat / IA 3873674 Michael A. Ondik

Right Engine — Continental Motors IO-470-L · S/N 297559-R

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
No Evidence Found						
2009-19-07 10/07/2009	EQ3 cylinders					
Complied With						
70-14-07 11/22/1974	Fuel Injection Pump	07/17/2009, ACTT 711.1	Complied with at overhaul per TCM SB M70-10 R1	No		CRS MW2R020L G&N Aircraft Inc.
88-03-06 04/15/1988 (overhaul statement)	Oil Filter	07/17/2009, 711.1	Overhaul entry: "All applicable Airworthiness Directives and Manufacturer's Service Bulletins are in compliance as of the date of overhaul."			C.R.S. # MW2R020L / -
91-19-03 09/29/1991 (overhaul statement)	Oil Filter	07/17/2009, 711.1	Overhaul entry: "All applicable Airworthiness Directives and Manufacturer's Service Bulletins are in compliance as of the date of overhaul."			C.R.S. # MW2R020L / -
93-08-17 08/23/1993 (overhaul statement)	Oil Pick-Up Tube	07/17/2009, 711.1	Overhaul entry: "All applicable Airworthiness Directives and Manufacturer's Service Bulletins are in compliance as of the date of overhaul."			C.R.S. # MW2R020L / -
2010-11-04 06/16/2010 **(L and R differ — review)**	Hydraulic lifters	11/30/2009, 2754.5	Complied with predecessor Emergency AD 2009-24-51 per TCM MEB09-08 by removing all intake lifters and installing overhauled lifters P/N 628488	No		CRS NF2R029L Bruce P. Rebechini
2023-17-04 10/26/2023	Reciprocating Engine Oil System	12/15/2025, ACTT 4589.5	Complied with per Stratus SB-001 Rev D (copper gasket installed on F&M oil filter adapter)	No		A&P 2733194 Kurt Moffat / IA 3873674 Michael A. Ondik

Right Engine — Continental Motors IO-470-L · S/N 297559-R (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Not Applicable (N/A)						
72-20-02 10/02/1974	Cylinders	07/17/2009, 711.1	Recorded in logbook as N/A by date of manufacture per SB M73-2	No		CRS MW2R020L G&N Aircraft Inc.
77-05-04 03/11/1977	Crankshaft		N/A by aircraft serial number (applies to Beech 95-B55 S/N TC-2003 through TC-2053; aircraft is S/N TC-1993)	No		
79-05-09 03/12/1979	Oil Pump Assembly Or Oil Pressure Relief Valve Screw And/Or Plunger		N/A by engine serial number (S/N 297559-R is not in affected serial number range)	No		
93-10-02 08/12/1993	Missing Cylinder Valve Retainer Key	07/17/2009, 711.1 ACTT	Recorded as N/A by date per SB M93-12 (engine accumulated 25 or more hours TIS prior to AD effective date)	No		CRS MW2R020L G&N Aircraft Inc
95-21-15 11/28/1995	Aviation Gasoline		Aircraft N155JA not listed in AD applicability (applies only to specific listed aircraft tail numbers)	No		
97-21-02 10/27/1997	Cylinders	07/17/2009, 711.1 ACTT	Recorded as N/A by new cylinder kits installed at overhaul per CSB97-10A	No		CRS MW2R020L G&N Aircraft Inc
98-01-08	Exhaust Roller Rocker Arm	07/17/2009, 711.1	N/A by P/N (PE92E rocker arms not installed)	No		CRS MW2R020L Dan Morgan
99-19-01 09/30/1999	No. 2 and No. 5 Crankshaft Inspections	07/17/2009, 711.1	N/A by S/N (Not in affected serial number range per MSB 99-3C)	No		CRS MW2R020L Dan Morgan
2000-23-21 12/12/2000	Crankshaft	07/17/2009, 2754.5	Engine and crankshaft date of manufacture or overhaul outside affected range (April 1, 1998 to March 31, 2000); recorded as N/A by date per TCM SB 00-5D	No		CRS MW2R020L G&N Aircraft Inc.
2012-03-06 02/24/2012	Fuel servo diaphragm		Equipment not installed (engine equipped with Continental fuel injection system, not AFS fuel servo)	No		
2022-16-03 08/15/2022	Engine (RECIPROCATING)	12/15/2025, Hobbs 4589.5	Logbook entry records AD as not applicable (affected S-1200 series magneto serial numbers not installed)	No		A&P 2733194 Kurt Moffat and IA 3873674
2023-02-12 02/17/2023	Engine Air Intake System		Equipment not installed (no affected SAP cylinder assembly or intake valve lot 19077 O installed on or after January 20, 2022)	No		
2023-05-16 03/15/2023	Reciprocating Engine Power Section	12/15/2025, ACTT 4589.5	Determined not applicable per logbook entry (crankshaft not in affected S/N or manufacture date range)	No		A&P 2733194 Kurt Moffat / IA 3873674 Michael A. Ondik

Left Propeller — McCauley 3AF32C504-C / 82NEA-4 · S/N 080816

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Not Applicable (N/A)						
83-13-06 07/05/1983	Spinner		S/N 080816 was manufactured in 2008 and is not within the serial number range in McCauley SB 147.	No		
2003-13-17 07/18/2003	Propeller blade		Not applicable; S/N 080816 not listed in Table 1 and unit not returned to service by T and W Propellers, Inc.	No		
2005-14-11 08/17/2005	Failed propeller blade		Left propeller was manufactured in July 2008 and never serviced by Southern California Propeller Service.	No		

Right Propeller — McCauley 3AF32C504-C / 82NEA-4 · S/N 080817

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Not Applicable (N/A)						
83-13-06 07/05/1983	Spinner		S/N 080817 was manufactured in 2008 and is not within the serial number range in McCauley SB 147.	No		
2003-13-17 07/18/2003	Propeller blade		Propeller S/N 080817 is not listed in Table 1 and was not returned to service by T and W Propellers.	No		
2005-14-11 08/17/2005	Failed propeller blade		Right propeller was manufactured in July 2008 and never serviced by Southern California Propeller Service.	No		

Appliances

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
No Evidence Found						
59-24-03	Safety Belts		No logbook entry of compliance found	No		
63-09-01	Fuel Flow Transmitters			No		
70-22-04 05/19/1971	Circuit Breakers					
77-12-05 05/12/1978	Oil Filters			No		
78-25-03 01/15/1979	Hose Assemblies					
79-07-02 04/03/1979	Batteries					
79-13-08	Dry Air Pumps					
79-16-02 08/02/1979	Safety Belt Assemblies					

Appliances (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
No Evidence Found (continued)						
79-18-05 02/28/1980	Batteries					
86-05-02 05/28/1986	Altimeters			No		
87-06-09 04/27/1987	Circuit Breakers		No logbook entry records compliance	No		
87-17-06 09/22/1987	Occupant Restraint System Assemblies		No logbook entry records compliance	No		
87-20-05 10/26/1987	Lap Belt Assemblies		No logbook entry records compliance	No		
89-09-02 05/24/1989	Safety Belts		No logbook entry records compliance	No		
97-11-10 06/23/1997	Portable Oxygen Masks			No		
97-16-10 09/18/1997	Filters			No		
97-18-03 09/22/1997	Cone and Seal Assemblies			No		
98-23-01 11/20/1998	Dry Air Pumps, Conversion Kits, and Coupling Kits			No		
2011-14-08 08/19/2011	Oxygen		No logbook entry records compliance or installation of affected B/E Aerospace oxygen mask assemblies	No		
2012-02-08 03/13/2012	Navigation		No logbook entry records compliance or installation of affected ACSS TCAS units	No		
2024-26-02 03/07/2025	Cabin Equipment/Furnishings					
2025-26-06 01/14/2026	Oxygen					
2026-03-09 03/12/2026	Oxygen					
Recurring						
76-07-12 08/30/1977	Ignition Switches	12/15/2025, 4589.5	Operational check of Bendix magneto switches	Yes	4689.5	A&P 2733194 IA Kurt Moffat
84-26-02 01/29/1985	Paper Induction Air Filters	1-2-86, 1468	Replaced L/H engine filter; R/H engine PCW 10-9-85	Yes	1968 ACTT	CRS 4308 D. Willson
2004-21-05 11/19/2004	B-Seires Combustion Heaters	12/15/2025, 4589.5	Pressure decay test performed on combustion tube	Yes	1655.1 heater hours or 12/2027	A&P 2733194 IA Kurt Moffat

Appliances (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Complied With						
74-26-09 12/24/1974	Magnetos	10/26/2022, -	Complied with drive shaft bushing requirement IAW Bendix SB 556B	No		A/P 1862854
80-16-05 08/11/1980	Oxygen Regulators	11-6-80, 777.1	Overhauled oxygen regulator	No		CRS 3786 B. Heilman
82-13-01 06/28/1982	Magnetos	07/16/2009, -	Complied with per Bendix SB 613 by installing new distributor blocks at engine overhaul	No		CRS MW2R020L Dan M.
82-20-01 06/14/1983	Magnetos	07/16/2009, -	Complied with per Bendix SB 623 by installing new cam assembly at engine overhaul	No		CRS MW2R020L Dan M.
94-01-03 R2 06/28/1995	Magnetos	07/16/2009, 3092.4	PCW per TCM MSB644 at engine overhaul	No		CRS MW2R020L G&N Aircraft Inc.
94-06-09 05/20/1994	Magnetos	07/16/2009, 2754.5	TCM CSB641	No		CRS MW2R020L G&N Aircraft Inc
Not Applicable (N/A)						
50-04-01	Ignition Switches		Briggs & Stratton Type A-8 ignition switch not installed	No		
50-05-02	Push-Pull Controls		Make/model: DRS lists only other aircraft, engines or propellers (Textron Aviation Inc.; Shakespeare Products Company; Sierra Hotel Aero, Inc.), not this aircraft's 95-B55, IO-470-L, 3AF32C504-C			
50-12-01	Propeller Blade		Hamilton Standard 11C1 propellers and W-670 engines not installed	No		
50-18-03	Model M-264 Safety Belts		Air Associates Model M-264 safety belts not installed	No		
50-48-02	Receivers		Collins Model 51R-1 or 51R-2 receivers not installed	No		
50-52-01	Blades		Make/model: DRS lists only other aircraft, engines or propellers (The Boeing Company; Hamilton Standard; Kelowna Flightcraft R & D Ltd.; Martin-M…), not this aircraft's 95-B55, IO-470-L, 3AF32C504-C			
51-26-02	Automatic Pilots		Lear L-2 series automatic pilots not installed	No		
52-13-01	Radio Receivers		Collins Model 51R-1 and 51R-2 receivers not installed	No		
53-26-01	Ignition Switch		Briggs & Stratton AAF Type B-5 ignition switch not installed	No		
54-04-01	Spark Plugs		AC LA-87 spark plugs not installed	No		
54-20-01	Safety Belts		Aircraft Belt & Trim Model LBM-1900 safety belts not installed	No		

Appliances (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Not Applicable (N/A) (continued)						
54-21-01	AC Diaphragm Type Fuel Pumps		AC diaphragm type fuel pumps not installed	No		
55-08-01	Safety Belt Buckles		Beech safety belt buckle P/N 113652 not installed	No		
55-26-02	Fuel Pumps		Thompson TF-1100-2 and TF-1100-M2 fuel pumps not installed	No		
56-19-02	Blade		Applies only to Boeing 377 aircraft; model and equipment not installed	No		
56-20-06	Gear Shafts		Make/model: DRS lists only other aircraft, engines or propellers (Curtiss-Wright/Marquette, Inc.; Hamilton Standard), not this aircraft's 95-B55, IO-470-L, 3AF32C504-C			
56-21-04	Safety Belts		Russell RM-3 and RM-4 safety belts with Rusco Tog-L-Lok buckles not installed	No		
56-22-01	Rubber Accessories		Hamilton Standard aluminum alloy propeller blades not installed	No		
57-13-05	Propeller Shank		Hamilton Standard aluminum alloy blades and Hydromatic propellers not installed	No		
57-14-02	Safety Belts		Davis Aircraft Products Model FDC-1650 safety belts not installed	No		
57-16-04	Governors		Hamilton Standard Model 4U18 or 5U18 governors not installed	No		
58-03-02	Governors		Hamilton Standard Model 4U18 or 5U18 governors not installed	No		
58-18-01	Governor		Make/model: DRS lists only other aircraft, engines or propellers (Curtiss-Wright/Marquette, Inc.; Hamilton Standard), not this aircraft's 95-B55, IO-470-L, 3AF32C504-C			
58-19-02	Blades		Hamilton Standard 2J17 propeller blades not installed; applies to Boeing 377 aircraft	No		
58-22-01	Blades		Hamilton Standard 6800, 6900, or 7000 series propeller blades not installed	No		
58-24-01	Blades		Hamilton Standard 2H17 series hollow steel propeller blades not installed	No		

Appliances (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Not Applicable (N/A) (continued)						
59-10-05	Governors.		Make/model: DRS lists only other aircraft, engines or propellers (Curtiss-Wright/Marquette, Inc.; Hamilton Standard), not this aircraft's 95-B55, IO-470-L, 3AF32C504-C			
60-03-04	Propeller Blades		Make/model: DRS lists only other aircraft, engines or propellers (The Boeing Company; Hamilton Standard), not this aircraft's 95-B55, IO-470-L, 3AF32C504-C			
61-08-02 10/26/1976	Safety Belts		Rupert Model 50, N50, 65, 80, or S-2194 safety belts not installed	No		
61-20-01 10/24/1961	Safety Belts		Auto Crat Model BN 1-1700 series safety belts not installed	No		
61-20-03 10/20/1961	Safety Belts		Rusco Model RM23 P/N SB1709 safety belts not installed	No		
62-06-02 04/10/1962	Receivers		EDO Model 345 or 345A Loran A receiver not installed	No		
62-23-01 11/19/1962	Safety Belts		Auto Crat Model BN 1-2001, BN 3-1501, BN 3-6001, or BN 3-7001 series safety belts not installed	No		
62-24-05 12/04/1962	Safety Belts		Equipment not installed (Mareco Model 15-1 safety belts not installed)	No		
64-01-01 01/09/1964	Vacuum Pumps		Equipment not installed (affected Airborne vacuum pump models/serial numbers not installed)	No		
64-03-03 03/01/1964	Blades		Make/model: DRS lists only other aircraft, engines or propellers (The Boeing Company; Hamilton Standard; Kelowna Flightcraft R & D Ltd.; Lockheed…), not this aircraft's 95-B55, IO-470-L, 3AF32C504-C			
64-10-03	Safety Belts		Equipment not installed (Davis Aircraft P/N FDC-2700 series safety belts not installed)	No		
64-13-04 06/18/1964	Actuating Valves		Equipment not installed (inflatable escape slides or life rafts with Walter Kidde actuating valves not installed)	No		
65-02-03	Turbochargers		Aircraft model not affected and equipment not installed (Beechcraft 95-B55 not in applicability; Rajay 315A10 turbochargers not installed)	No		
65-06-04 03/06/1965	Survivor Locator Light		Equipment not installed (Eureka Williams survivor locator light not installed)	No		

Appliances (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Not Applicable (N/A) (continued)						
65-21-01 01/28/1975	Starters		Applies to starters installed on Lycoming engines only (aircraft has Continental IO-470-L engines)	No		
66-07-03 04/03/1966	Engine Gage Units		Equipment not installed (applies to Thomas A. Edison/Garwin engine gage units date stamped before April 1, 1961)	No		
67-01-04 01/02/1967	Oil Filters		Equipment not installed (Superior Flow oil filters under STC SE325SW, SE419SW, or SA401SW not installed)	No		
67-02-04 06/23/1970	Accessory Gear Boxes		Make/model: DRS lists only other aircraft, engines or propellers (British Aerospace (Commercial Aircraft) Ltd; Dowty Rotol; Gulfstream Aerospace ...), not this aircraft's 95-B55, IO-470-L, 3AF32C504-C			
67-18-05 06/30/1967	Seats		Equipment not installed (TECO Model 603 seats not installed)	No		
67-26-04	Altimeters		Aircraft S/N TC-1993 outside applicable serial number range (TC-1005 through TC-1039) and Model 22-374 altimeter not installed	No		
69-24-05 12/04/1969	Altimeters		Affected Kollsman altimeter models not installed	No		
70-15-18 08/31/1970	Automatic Pilot and Automatic Aileron Stabilizer Instruments		Affected Mitchell or Piper autopilot instruments not installed	No		
70-22-02 11/04/1970	Fuel Selector Valves		Make/model: DRS lists only other aircraft, engines or propellers (Piper Aircraft Inc.), not this aircraft's 95-B55, IO-470-L, 3AF32C504-C			
70-26-02 12/27/1970	Propeller Governors		Applies to single-engine aircraft; aircraft is twin-engine and affected Woodward governors not installed	No		
71-06-08 06/08/1971	Wheel/Brake Assembly		Affected Cleveland wheel/brake assembly P/N 3080C/37-200A not installed	No		
71-14-03 07/02/1971	Regulator		International Inflatables Company regulator P/N 68240 not installed	No		
72-02-06 01/31/1972	Automatic Pilot Instruments		Make/model: DRS lists only other aircraft, engines or propellers (Cessna Aircraft Company; Mitchell Industries, Inc.), not this aircraft's 95-B55, IO-470-L, 3AF32C504-C			

Appliances (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Not Applicable (N/A) (continued)						
72-04-02 03/04/1972	Wheel Assemblies		Affected Bendix wheel assemblies (P/N 2601901 and P/N 2603561) not installed	No		
72-15-02 09/01/1972	Alternator Cooling Fans		Affected Prestolite alternator cooling fans (P/N PU1605 and PU1605A) and alternator models not installed	No		
72-19-04 02/01/1974	Battery		Aircraft equipped with lead-acid batteries (Concorde RG-25), not nickel-cadmium batteries	No		
72-22-02 11/15/1972	Fiberglass		Aircraft is of all-metal construction and not covered with fiberglass using the Razorback method	No		
73-01-03 01/17/1973	Life Jackets		Air Cruisers Model AD-8 life jackets not installed	No		
73-07-02 03/29/1973	Emergency Locator Transmitters		Garrett Model Rescu/88 Emergency Locator Transmitters not installed	No		
73-11-03 06/22/1973	Regulator		Equipment not installed (International Inflatables Company regulator P/N 70003 for passenger evacuation slides)	No		
73-13-11 06/29/1973	Automatic Pilot Instruments		Make/model: DRS lists only other aircraft, engines or propellers (Textron Aviation Inc.; Mitchell Industries, Inc.), not this aircraft's 95-B55, IO-470-L, 3AF32C504-C			
74-08-01 04/09/1974	Autopilot Servo Actuators		Equipment not installed (ARC PA-500A, PA-520A, or PA-520B autopilot servo actuators for Cessna autopilots)	No		
74-13-06 06/24/1974	Main Wheel Assemblies		Equipment not installed (McCauley main wheel assemblies P/N D-30063-1, -2, or -4)	No		
74-17-01 09/16/1974	Regulator		Equipment not installed (Sargent Industries Pico Division regulator P/N 30001 for evacuation slides)	No		
74-18-05 08/28/1974	Magnetos		Equipment not installed (Slick magnetos; aircraft is equipped with Bendix S-1200 series magnetos)	No		
74-18-15 01/23/1975	Emergency Locator Transmitter		Equipment not installed (Leigh Systems Sharc 7 Series ELT)	No		
74-19-02 09/13/1974	Emergency Locator Transmitters		Pathfinder Corporation ELT not installed	No		

Appliances (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Not Applicable (N/A) (continued)						
74-20-10 12/30/1977	Emergency Locator Transmitter		Leigh Systems Sharc 7 ELT not installed	No		
74-24-07	Rescue Locator Beacons		Chromalloy RLB-6 beacon not installed	No		
74-24-10 11/27/1974	Wheel Assembly		BFGoodrich P/N 3-1306 wheel assembly not installed	No		
74-24-13 12/05/1974	Altimeters		Installed altimeter serial numbers not in affected serial number range	No		
75-05-05 03/26/1975	Wheel Assemblies		Goodyear main wheel assemblies P/N 5000757-1 and -2 not installed (typically used on DC-10 aircraft)	No		
75-05-07 02/28/1975	Navigation System		King KCS-55 pictorial navigation system (KG-102/KI-525) in affected serial number range not installed	No		
75-05-14 03/06/1975	Altitude Reporting Altimeters		Kollsman Type B4545110001 and B4545110011 altitude reporting altimeters in affected serial number range not installed	No		
75-12-07 06/06/1975	Governors		McCauley propeller governor models (DCF/DCFS/DCFU/DCFUS290D1A/T2) in affected serial number range not installed	No		
75-12-10 06/11/1975	Autopilots		Make/model: DRS lists only other aircraft, engines or propellers (M7 Aerospace LLC; Twin Commander Aircraft LLC; Viking Air Limited; Textron Avia…), not this aircraft's 95-B55, IO-470-L, 3AF32C504-C			
75-22-13 12/01/1975	Inertial Navigation Systems		Litton LTN-72 inertial navigation system not installed	No		
75-22-22 11/10/1975	Compressed Gas Cylinders		Aircraft category (applies to transport category airplanes); affected Pressed Steel Tank DOT-3HT-3000 gas cylinders not installed	No		
76-02-07 02/02/1976	Alternators		Equipment not installed	No		
76-07-02 04/06/1976	Emergency Evacuation Systems		Aircraft model not affected and evacuation slides not installed	No		
76-16-02 08/11/1976	Engine Driven Pumps		Affected pre-1966 Airborne vacuum pumps not installed	No		
77-02-08 02/01/1977	Batteries		Narco ELT-10 77 equipment not installed	No		
77-05-05 05/09/1978	Unapproved Appliances		Aircraft model not affected and Boeing appliances not installed	No		

Appliances (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Not Applicable (N/A) (continued)						
77-15-10 08/04/1977	Airspeed Indicators		Filotechnica Salmoiraghi airspeed indicators not installed	No		
77-16-10 09/08/1977	Navigation Systems		Edo-Aire Mitchell NSD-360 navigation system not installed	No		
78-01-01 01/30/1978	Sensors		Make/model: DRS lists only other aircraft, engines or propellers (The Boeing Company; Lockheed Martin Corporation; Sundstrand), not this aircraft's 95-B55, IO-470-L, 3AF32C504-C			
78-05-06 06/30/1978	Flexible Fuel Cells	04/21/1978, 306.0	Aircraft S/N not affected per Beech Service Instruction 0895	No		A&P 479768745 A. Bajc
78-18-04 09/09/1978	Magnetos		Bendix D-2000 and D-2200 series magnetos not installed	No		
78-20-12 10/05/1978	Aircraft Tires		Firestone 18x5.5 P/N 00490 tires not installed	No		
79-12-07 06/19/1979	Magnetos		Affected Bendix D-2000 and D-2200 series magnetos and part numbers not installed (aircraft equipped with Continental IO-470-L engines and Bendix S-1200 series magnetos)	No		
79-18-06	Magnetos		N/A - Bendix D-2000 and D-2200 series magnetos not installed	No		
79-21-08 10/24/1979	Fuel Injection Systems		N/A - Bendix RSA fuel injection system not installed	No		
79-26-03 12/26/1979	Fuel Injector Systems		N/A - Bendix RSA-5AD1 fuel injector units not installed	No		
79-26-05 01/03/1980	Oil and Fuel System Hoses		N/A - Aircraft Metal Products hose P/N 762506 not installed	No		
80-01-05 R1 07/10/1980	Restraint Systems		N/A - Pacific Scientific rotary buckles manufactured through 1970 not installed	No		
80-05-02 02/27/1980	Safety Belt Assemblies		N/A - Hamill Model GA-4 and GA-5 safety belt assemblies not installed	No		
80-05-04 03/10/1980	Seat Belts and Harnesses		EON Model E2900 and E8000 seat belts and harnesses not installed	No		
80-06-05 03/28/1980	Magnetos		Affected Slick magneto models and impulse couplings not installed	No		
80-08-04 04/17/1980	Auxiliary Fuel System		Make/model: DRS lists only other aircraft, engines or propellers (Bell Helicopter Textron Canada Limited; Chadwick, Inc.; MD Helicopters, Inc.), not this aircraft's 95-B55, IO-470-L, 3AF32C504-C			
80-08-14 04/22/1980	Carburetor Air Inlet Filter		Pure-Air, Inc. carburetor air inlet filter (STC SA69NW) not installed	No		

Appliances (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Not Applicable (N/A) (continued)						
80-12-15 07/25/1980	Pitot-Static Probes		Rosemount Model 856 AE pitot-static probes not installed	No		
80-17-04 08/13/1980	Fuel Flow Transducers		Aerosonic fuel flow transducers P/N 33184-1 and 32622-6 not installed	No		
80-17-14 08/21/1980	Magnetos		Equipment not installed (Bendix D-2000 and D-2200 series magnetos not installed)	No		
80-18-05 09/29/1980	Flight Director Systems		Equipment not installed (Sperry STARS flight director systems not installed)	No		
80-19-19 09/25/1980	Area Navigation Systems		Equipment not installed (Jet Electronics Model DAC-2000 or DAC-7000 RNAV systems not installed)	No		
80-22-06 11/25/1980	Aircraft Seats		Equipment not installed (Universal Oil Products Model 900 series aircraft seats not installed)	No		
80-25-07 R1 09/24/1981	Oil Coolers		Equipment not installed (affected Stewart-Warner oil coolers not installed)	No		
81-01-06 01/12/1981	Autopilot		Equipment not installed (Bendix M-4/YD-4 autopilot primary servos not installed)	No		
81-03-03 01/28/1981	Brake Assemblies		BF Goodrich brake assemblies P/N 2-1195-7, 2-1195-8, 2-1367, 2-1147, and 2-1190 not installed (applies to Boeing 727 and Lockheed L-1011)	No		
81-06-02 03/19/1981	Emergency Descent Devices		Make/model: DRS lists only other aircraft, engines or propellers (Airbus; The Boeing Company; Frost Engineering; Lockheed Martin Corporation), not this aircraft's 95-B55, IO-470-L, 3AF32C504-C			
81-12-06 R1 11/12/1981	Magnetos		Bendix D-3000 and D-3200 series magnetos not installed (applies to Lycoming TIO/LTIO-540-J2BD engines)	No		
81-15-03 07/20/1981	Engine Inlet Air Filters		Make/model: DRS lists only other aircraft, engines or propellers (Cessna Aircraft Company; Mooney Aviation Company Inc; Mooney Mite Aircraft Corp…), not this aircraft's 95-B55, IO-470-L, 3AF32C504-C			
81-16-05 08/06/1981	Magnetos		Slick magnetos not installed; recorded as N/A in logbook	No		A&P 1862835 T.B. Norman

Appliances (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Not Applicable (N/A) (continued)						
81-18-07 09/10/1981	Tricycle Landing Gear		Make/model: DRS lists only other aircraft, engines or propellers (Textron Aviation Inc.; Volpar, Inc.), not this aircraft's 95-B55, IO-470-L, 3AF32C504-C			
81-19-04 09/17/1981	Hose Assembly		Rajay STC turbocharger hose assemblies not installed on aircraft	No		
81-21-05 10/19/1981	Battery Packs		Artex battery pack P/N 00-21-006 and Emergency Beacon Corporation ELT not installed on aircraft	No		
81-25-01 12/07/1981	Flyweights		Make/model: DRS lists only other aircraft, engines or propellers (Maule Aerospace Technology, Inc.; Woodward Governor Company), not this aircraft's 95-B55, IO-470-L, 3AF32C504-C			
82-11-05 06/09/1982	Magnetos		Bendix D-2000 and D-2200 series magnetos not installed on aircraft	No		
82-12-04 06/07/1982	Combined Power Turbine and Propeller Governor Assembly		Equipment not installed (applies to Detroit Diesel Allison 250 series engines)	No		
82-18-10 10/04/1982	Aircraft Seats		Make/model: DRS lists only other aircraft, engines or propellers (The Boeing Company; Flight Equipment and Engineering Corporation), not this aircraft's 95-B55, IO-470-L, 3AF32C504-C			
82-27-03 12/30/1982	Turbochargers		Equipment not installed (applies to Rajay turbochargers; aircraft has naturally aspirated Continental IO-470-L engines)	No		
83-21-06 R1 04/26/1984	Crew Seats		Equipment not installed (applies to AMI Crew Seats Model 716 and 865 series)	No		
83-26-03 02/21/1984	Aircraft Tires		Equipment and part number not installed (applies to specific BF Goodrich tires P/N 038-627 and 033-631)	No		
84-18-07 09/21/1984	Discharge Cartridges		Affected Walter Kidde and Overland Aviation discharge cartridges not installed	No		
85-06-02 03/19/1985	Main Landing Gear Wheel Assemblies		Make/model: DRS lists only other aircraft, engines or propellers (BFGoodrich; The Boeing Company; Lockheed Martin Corporation), not this aircraft's 95-B55, IO-470-L, 3AF32C504-C			

Appliances (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Not Applicable (N/A) (continued)						
85-07-03 R1 09/14/1986	Instrument Landing System		Make/model: DRS lists only other aircraft, engines or propellers (Airbus Helicopters; Sikorsky Aircraft Corporation; Sperry Flight Systems), not this aircraft's 95-B55, IO-470-L, 3AF32C504-C			
85-09-01 05/13/1985	Harness/Container Assemblies		Affected Airotech Force I(A) harness/container assemblies not installed	No		
85-22-10 12/31/1985	Flight Director Indicators and Horizontal Situation Indicators		Affected Collins flight director and HSI indicators not installed	No		
85-23-07 01/27/1986	Autopilot Systems		Affected King KFC 150/KAP 150/KAP 100 autopilot systems not installed	No		
85-25-02 01/27/1986	Autopilot Systems		Make/model: DRS lists only other aircraft, engines or propellers (King Radio Corporation; Mooney Aviation Company Inc; SOCATA), not this aircraft's 95-B55, IO-470-L, 3AF32C504-C			
85-26-01 02/06/1986	Safety Belts		Affected Secur Aiglon Model 343 safety belts not installed	No		
86-13-04 R3 02/24/1988	Cylinder Assemblies		Aircraft equipped with Continental IO-470-L engines, which are not included in the engine model applicability of this AD	No		
86-14-01 07/14/1986	Attitude Heading Reference System		Sperry AHZ-600 Attitude Heading Reference System is not installed on this aircraft	No		
86-25-01 01/06/1987	Navigation Receivers		Collins Model 51RV-4 VOR-ILS navigation receiver is not installed on this aircraft	No		
87-04-19 03/18/1987	Safety Belt Assemblies		EON Corporation TSO C22 safety belt assemblies with E6000 buckles are not installed on this aircraft	No		
87-06-07 04/06/1987	Seat Track Fittings		Weber Aircraft TSO C39a seats and affected Ancra seat track fittings are not installed on this aircraft	No		
87-16-07 08/20/1987	Electronic Flight Instrument Systems		Equipment not installed (Honeywell/Sperry EDZ series EFIS not installed)	No		
87-23-01 12/10/1987	Wire Bundles		Make/model: DRS lists only other aircraft, engines or propellers (The Boeing Company; Heath Tecna), not this aircraft's 95-B55, IO-470-L, 3AF32C504-C			

Appliances (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Not Applicable (N/A) (continued)						
89-03-01 R1 11/13/1989	Radial Tires		Equipment not installed (applies to Goodyear 32x8.8R16 radial tires P/N 328Q08G2)	No		
90-01-03 02/05/1990	Attitude and Heading Reference System		Equipment not installed (Honeywell AH-600 AHRS not installed)	No		
90-06-13 03/30/1990	Vertical Gyro		Equipment not installed (Honeywell Model VG-14A vertical gyro P/N 7000622-901 not installed)	No		
90-07-08 R1 07/02/1990	Fluorescent Lighting and Remote Power Units		Equipment not installed (SELA fluorescent lighting connectors/RPUs not installed)	No		
90-09-08 05/29/1990	Crew Seats		Equipment not installed (IPECO TSO-C39a crew seats not installed)	No		
90-09-10 05/30/1990	Circuit Breakers		Equipment not installed (Texas Instruments 6TC6/6TC20 circuit breakers not installed)	No		
91-02-05 01/14/1991	Parachute Canopies		Equipment not installed (GQ Security Parachutes Model 79A1684-( ) parachute canopies not installed)	No		
91-08-04 05/06/1991	Pilot and Co-Pilot Seats		Aviatech Model 394 seats not installed	No		
92-11-09 05/28/1992	Transponders		Rockwell Collins TPR-720 transponder not installed	No		
92-16-06 08/31/1992	Aircraft Starters		Garrett AirResearch starters not installed	No		
92-16-15 09/01/1992	Oxygen Mask Connectors		Scott Aviation P/N 289-57 oxygen mask connectors not installed	No		
92-18-08 10/02/1992	Flight Control Systems		Make/model: DRS lists only other aircraft, engines or propellers (Piper Aircraft Inc.), not this aircraft's 95-B55, IO-470-L, 3AF32C504-C			
93-04-02 03/26/1993	Transponders		Rockwell Collins TDR-94D transponder not installed	No		
93-05-06 04/29/1993	Ignition Switches		ACS and Gerdes ignition switches not installed	No		
93-07-05 05/10/1993	Pilot and Co-Pilot Seats		AMI Industries Model 1108 pilot and co-pilot seats not installed	No		
93-08-02 05/27/1993	Reserve Pilotchutes		Rigging Innovations Skyhook reserve pilotchutes P/N 2233-( ) not installed	No		
93-09-07 05/11/1993	Fire Extinguishers		Pacific Scientific fire extinguishers listed in Alert SB 26A1106 not installed	No		

Appliances (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Not Applicable (N/A) (continued)						
93-11-11 06/21/1993	Fuel Pumps		Affected AC, Textron Lycoming, or Rajay/Rotomaster diaphragm fuel pumps overhauled by Aero Accessories Inc. not installed	No		
93-24-16 02/04/1994	Protective Breathing Equipment		Puritan Bennett crewmember protective breathing equipment units 119003 and 119003-01 not installed	No		
94-06-04 05/23/1994	Mask Regulators		EROS series MF10 full face quick donning mask regulators not installed	No		
94-20-07 12/27/1994	Passenger Oxygen System		Make/model: DRS lists only other aircraft, engines or propellers (The Boeing Company; PTC Aerospace), not this aircraft's 95-B55, IO-470-L, 3AF32C504-C			
94-21-06 11/25/1994	Lap Belt Assemblies and Restraint Systems		Affected Pacific Scientific lap belt assemblies not installed	No		
95-01-01 02/06/1995	Transponders		Terra TRT 250 series transponders not installed	No		
95-24-10	Tires		Michelin P/N 028-520-1 tires not installed	No		
96-09-06 06/07/1996	Air Filter Assemblies		Installed Brackett BA-7610 / BA-7605 air filter assembly is not an affected part number	No		
96-12-04 08/12/1996	Pistons		Equipment not installed; aircraft equipped with TCM IO-470-L engines, AD applies to Superior Air Parts pistons on TCM O-470-K, -L, -R engines	No		
96-12-09 07/29/1996	Passenger Seat		Equipment not installed; PTC Model 950 series passenger seats with footrest assembly not installed	No		
96-12-22 07/31/1996	Full Flow Engine Oil Adapter		Equipment not installed; affected Cessna oil filter adapters not installed (equipped with F&M Enterprises C6LC-5 adapters per STC SE09356SC)	No		
96-21-13 11/12/1996	Attitude and Heading Reference System		Equipment not installed; LITEF GmbH AHRS Model LCR-92, LCR-92S, or LCR-92H not installed	No		
97-04-15 03/07/1997	Fire Extinguisher Bottle Cartridges		Equipment not installed; Pacific Scientific P/N 13083-10 or 13083-25 fire extinguisher bottle cartridges not installed	No		

Appliances (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Not Applicable (N/A) (continued)						
97-05-03 R1 04/20/1999	Global Positioning Systems		Equipment not installed; AlliedSignal GNS-XL or GNS-XLS GPS flight management system not installed	No		
97-08-06 R1 08/01/1997	Quick Connectors		Applies to gliders and sailplanes; equipment not installed	No		
98-08-20 06/02/1998	Autopilot Servo Actuators		Bendix/King KSA 470 autopilot servo actuators not installed	No		
98-14-03 08/16/1998	Transponders		Aircraft equipped with King KT 76 P/N 066-1034-01, not affected KT 76A P/N 066-1062-XX	No		
98-19-02 11/09/1998	Piston Pins		Engine model Continental IO-470-L not in AD applicability (applies to IO-360, LTSIO-360, TSIO-360 series)	No		
98-24-27 01/29/1999	Fire Extinguisher		Equipment not installed (applies to First Technology toilet compartment fire extinguishers)	No		
98-25-02 12/22/1998	Top-mounted Antenna		Equipment not installed (applies to BFGoodrich SKYWATCH SKY497 with top-mounted antenna)	No		
98-25-10 R1 01/14/2000	Seat Restraint Systems	04/13/00, 2772.4	Inspected and found not applicable by seat belt manufacturer	No		CRS CGHR812C Jason D. Staver
99-01-14 02/12/1999	Integrated Avionics Computers		Equipment not installed (applies to Honeywell IC-600 integrated avionics computers)	No		
99-04-04 02/25/1999	Impulse Coupling Pawl		Equipment not installed (applies to Textron Lycoming O-540/IO-540 engines equipped with Slick magnetos; aircraft has Continental IO-470-L engines)			
99-12-06 07/23/1999	Navigation Receivers		Equipment not installed (applies to AlliedSignal VN 411B VHF navigation receivers; not installed on aircraft)			
99-23-24 12/06/1999	Navigation Receivers		Equipment not installed (applies to AlliedSignal RIA-32A ILS navigation receivers; not installed on aircraft)			
99-24-10 01/14/2000	Standby Vacuum Systems		Equipment not installed (applies to Precise Flight Model SVS III standby vacuum systems; not installed on aircraft)			
99-25-07 12/23/1999	Main Brake Assemblies		Equipment not installed (applies to BFGoodrich main brake assemblies P/N 2-1598 or 2-1600 on Airbus A319/A320 airplanes; not installed on aircraft)			
2000-05-24 04/12/2000	Autopilot System		Honeywell KAP 140 or KFC 225 autopilot system not installed	No		

Appliances (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Not Applicable (N/A) (continued)						
2000-14-14 08/07/2000	Main Landing Gear (MLG)		BFGoodrich main brake assemblies P/N 2-1598-1 or 2-1600-1 not installed; applies to Airbus A319/A320 airplanes	No		
2001-10-09 06/15/2001	Automatic Flight Control Systems		Honeywell KC 225 automatic flight control system not installed	No		
2001-14-51 07/30/2001	UPS Aviation Technologies, Inc., Model Apollo SL30 VHF NAV/COMM Radio		UPS Aviation Technologies Model Apollo SL30 VHF NAV/COMM radio not installed	No		
2001-15-17 08/20/2001	Transponder Control Panels		Rockwell Collins CTL-92 transponder control panel not installed	No		
2001-18-05 09/24/2001	Flight Eagle Tires		Goodyear Flight Eagle tires P/N 348F83-2 not installed	No		
2002-13-07 08/09/2002	Inertial Reference Units (IRU)		Honeywell HG1075AB05 or HG1075GB05 Inertial Reference Unit (IRU) not installed	No		
2002-20-09 11/12/2002	Adaptive flight display units		Rockwell Collins AFD-3010 adaptive flight display unit not installed	No		
2002-21-01 11/27/2002	Electrical terminal contact pins		Britax Sell water boilers, coffee makers, or beverage makers not installed	No		
2002-22-12 12/13/2002	Titeflex hoses		Aircraft model and Continental IO-470 engines not in AD applicability	No		
2002-23-07 01/07/2003	Valve Stems of the Main Blast, Liquid Fire, and Pilot Light Valves		Cameron Balloons Mk1 or Mk2 burners not installed	No		
2002-26-03 02/18/2003	Brackett single screen air filter		Brackett P/N BA-2410 air filter assembly not installed	No		
2003-05-02 05/02/2003	Fuel hose		Equipment not installed; applies to balloons equipped with Lindstrand 3/8-inch fuel hoses	No		
2003-15-07 09/03/2003	Fuel nozzles		Equipment not installed; applies to Honeywell RE220 (RJ) APU	No		
2003-23-05 12/24/2003	Titeflex hoses		Equipment not installed; applies to specific Titeflex hoses used on Boeing aircraft	No		
2003-26-06 02/17/2004	Safety Belts and Restraint Systems		Equipment not installed; applies to Anjou Aeronautique Type 343 series safety belts	No		
2003-26-14 02/20/2004	Hand-Held Halon Fire Extinguishers		Equipment not installed; applies to Kidde Aerospace P/N 898052 hand-held halon fire extinguishers	No		

Appliances (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Not Applicable (N/A) (continued)						
2004-08-15 06/07/2004	TAWS8000 terrain awareness warning systems (TAWS)		Equipment not installed; applies to Goodrich TAWS8000 TAWS (P/N 805-18000-001)	No		
2004-08-16 06/01/2004	Transponders		Narco AT150 transponder not installed	No		
2004-13-20 08/03/2004	GPS navigation units		Garmin AT Apollo GX series GPS unit not installed	No		
2004-21-04 11/19/2004	Aircraft flight manual (AFM)		Becker AR 4201 VHF AM transceiver not installed	No		
2004-24-03 01/03/2005	Internal o-ring seal		Auxiliary Power Unit (APU) not installed	No		
2004-25-16 R1 06/20/2005	Fuel regulator shutoff valve	03/11/2002, 2905.2	Fuel regulator shutoff valve not installed on aircraft (recorded as N/A for predecessor AD 2001-17-13)	No		CRS UD2D209L Henry B. Burke
2005-01-19 02/23/2005	Mode S transponders		Garmin GTX 330 transponder removed on 10/09/2019 and replaced with Garmin GTX 345; affected equipment not installed	No		
2005-07-27 05/16/2005	Seat central crossmember		Aviointeriors Series 312 seats not installed on Beechcraft 95-B55	No		
2005-11-05 07/18/2005	Standby vacuum systems (SVS)		Precise Flight Model SVS I or SVS IA standby vacuum system not installed	No		
2005-12-06 07/19/2005	Riveted-impulse coupling assemblies and snap-ring coupling assemblies	07/16/2009, 3121.0	Applies only to Bendix magnetos on Lycoming 540 series engines; aircraft has Continental IO-470-L engines	No		CRS MW2R020L Dan M.
2005-20-26 11/16/2005	Seat attachments.		Aviointeriors Series 312 box mounted seats not installed on Beechcraft 95-B55	No		
2005-20-31 10/05/2005	Airplane Flight Manual (AFM)		Honeywell Flight Management System (FMS) not installed	No		
2005-23-11 12/14/2005	Compressor impeller assemblies		Hamilton Sundstrand APU not installed	No		
2005-25-08 01/23/2006	Electronic Flight Information System (EFIS)		Shadin ADC-2000 air data computer not installed	No		
2006-03-08 03/10/2006	Vacuum pumps		Aero Advantage ADV200 series vacuum pump not installed	No		
2006-08-03 05/18/2006	Bottom seat folding mechanisms		Sicma Aero Seat cabin attendant seats not installed	No		

Appliances (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Not Applicable (N/A) (continued)						
2006-10-21 06/22/2006	ECi connecting rods		Applies to Lycoming 360/540 engines; Continental IO-470-L engines installed	No		
2006-12-07 07/11/2006	ECi cylinder assemblies		Applies to Lycoming 320/360/540 engines; Continental IO-470-L engines installed	No		
2006-12-25 07/28/2006	Actuator nut assembly		Aircraft model and equipment not installed (applies to General Machine-Diecron actuator nut assemblies P/N GMD115-810029-17/-23 on King Air and 99 series)	No		
2006-17-13 09/27/2006	Replacing the existing attachment bolts for the seat belts with longer attachment bolts		Equipment not installed (applies to RECARO Model 3410 series seats)	No		
2006-18-08 10/11/2006	Nosewheel tires		Equipment not installed (applies to Goodyear P/N 217K22-1 aviation tires)	No		
2006-25-15 01/19/2007	two headrest bushings		Equipment not installed (applies to Sicma Aero Seat 133 series third occupant seats)	No		
2007-04-15 03/23/2007	Installing new tab locks		Equipment not installed (applies to Sicma passenger seats with aft track fittings P/N 90-000120-790-0)	No		
2007-04-19R1 05/07/2007	SAP cylinder assemblies	10/02/2009, ACTT 3121	Not applicable by cylinder manufacturer (Superior Air Parts cylinders not installed)	No		CRS NF2R029L Bruce P. Rebechini
2007-14-06 08/16/2007	Isolation diode		Honeywell CAS67A ACAS II system not installed	No		
2007-19-12 10/26/2007	SICMA Aero Seat		SICMA Aero Seat 50XXX passenger seats not installed	No		
2007-19-13 10/03/2007	Hydrolok retaining pin		B/E Aerospace Skyluxe II passenger seats not installed	No		
2009-05-05 04/03/2009	Primary Flight Displays		Avidyne Primary Flight Display not installed	No		
2009-05-08 04/20/2009	Global positioning system (GPS)		Trimble or FreeFlight Systems 2101 I/O Approach Plus GPS navigation system not installed	No		
2009-21-10 R1 02/04/2010	Oxygen		Affected AVOX Systems or B/E Aerospace oxygen cylinder assemblies not installed	No		
2009-26-12 02/04/2010	Cylinder assemblies		Equipment not installed; aircraft equipped with Continental IO-470-L engines, not Lycoming 320, 360, or 540 series engines with ECi cylinder assemblies	No		

Appliances (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Not Applicable (N/A) (continued)						
2010-01-03 01/20/2010	Fire Protection		Equipment not installed; Fire Fighting Enterprises Limited portable Halon 1211 fire extinguishers not installed	No		
2010-02-06 02/24/2010	Equipment/Furnishings		Aircraft model not affected; applies to ATR42 and ATR72 series airplanes	No		
2010-03-02 02/11/2010	D-Lok Hook assembly		Aircraft category and equipment not installed; applies to helicopters with Lifesaving Systems Corp. D-Lok hook assemblies on rescue hoists	No		
2010-04-16 03/08/2010	Fire protection		Equipment not installed; SICLI Type H1-10 AIR Halon 1211 portable fire extinguishers P/N 1708337B4 not installed	No		
2010-07-02 05/03/2010	Integrated navigation units (INUs)		Equipment not installed; Honeywell Primus II RNZ-850 or RNZ-851 integrated navigation units not installed	No		
2010-07-08 04/19/2010	Turbochargers		Equipment not installed (naturally aspirated Continental IO-470-L engines, no turbochargers installed)	No		
2010-09-04 05/14/2010	Navigation		Aircraft model and equipment not installed (applies to Honeywell Primus EPIC/APEX FMS on ERJ 170/190 and PC-12/47E)	No		
2010-11-05 07/06/2010	Oxygen		Equipment not installed (applies to AVOX Systems and B/E Aerospace 114/115 cu ft Type 3HT oxygen cylinders)	No		
2010-13-10 08/05/2010	Propeller governors		Equipment not installed (applies to Ontic P/N C210776, T210761, D210760, J210761 governors; N155JA uses McCauley/Woodward governors)	No		
2011-01-09 02/09/2011	Oxygen		Aircraft category and equipment not installed (applies to B/E Aerospace PBE units P/N 119003-11 on transport category airplanes)	No		
2011-12-01 08/01/2011	Equipment/Furnishings		Equipment not installed (applies to Koito Industries Ltd. seats and seating systems)	No		
2011-21-08 11/23/2011	Equipment/Furnishings		Aircraft category and model not affected (applies to transport category aircraft and Sicma seats 88xx-96xx; not installed on Beechcraft 95-B55)	No		

Appliances (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Not Applicable (N/A) (continued)						
2012-06-25 05/04/2012	Emergency Equipment		Aircraft model not affected (applies to Goodrich evacuation systems on Airbus A330 and A340 aircraft; not installed on Beechcraft 95-B55)	No		
2012-08-07 05/09/2012	Equipment/Furnishings		Aircraft model and equipment not affected (applies to Sicma Aero Seat 94xx series passenger seats on ATR42/72 aircraft; not installed on Beechcraft 95-B55)	No		
2012-10-52 06/26/2012	Turbochargers		Equipment not installed (N155JA is equipped with naturally aspirated Continental IO-470-L engines; Hartzell/HET turbochargers are not installed)	No		
2012-11-09 R1 07/27/2015	Oxygen		Applies to transport category airplanes in passenger-carrying operations (Part 121 or 129) with chemical oxygen generators in lavatories; aircraft is a Beechcraft 95-B55 Baron.	No		
2012-11-13 07/30/2012	High Landing Gear Aft Crosstube Assembly		Applies to High Landing Gear Aft Crosstube Assemblies on Agusta and Bell 412 series helicopters; equipment not installed on Beechcraft 95-B55 Baron.	No		
2012-14-15 07/19/2012	Navigation		Applies to Honeywell Model KGS200 Mercury 2 WAAS GNSSU (P/N 066-01201-0102 and 066-01201-0104); equipment not installed on N155JA.	No		
2012-17-01 09/13/2012	Landing gear		Applies to Goodyear new tire P/N 299K63-1 (size H29x9.0-15); equipment not installed on Beechcraft 95-B55 Baron.	No		
2012-22-06 12/14/2012	High Landing Gear Forward Crosstube Assembly		Applies to High Landing Gear Forward Crosstube Assemblies on Agusta and Bell helicopters; equipment not installed on Beechcraft 95-B55 Baron.	No		
2012-26-15 R1 12/03/2014	Navigation		Applies to Honeywell air data pressure transducers installed on specific aircraft models; equipment not installed on Beechcraft 95-B55 Baron.	No		
2013-03-10 03/19/2013	Hardware		Applies to Lindstrand Hot Air Balloons Ltd female ACME threaded hose connectors; equipment not installed	No		
2013-10-01 06/20/2013	Exterior lighting		Applies to Spectrolab Nightsun XP searchlight systems installed on helicopters; equipment not installed	No		

Appliances (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Not Applicable (N/A) (continued)						
2014-05-27 05/02/2014	Navigation		Applies to Rockwell Collins TPR-720 and TPR-900 Mode S transponders; equipment not installed	No		
2014-17-02 09/09/2014	Communications		Applies to Honeywell ASCa Inc. emergency locator transmitters; equipment not installed	No		
2014-18-01 10/14/2014	Navigation		Applies to Rockwell Collins TDR-94 and TDR-94D Mode S transponders; equipment not installed	No		
2015-08-07 06/16/2015	Oxygen		Applies to Zodiac Aerotechnics flightcrew oxygen mask regulators; equipment not installed	No		
2015-10-02 06/12/2015	Equipment/Furnishings		Equipment not installed (affected Zodiac Seats France passenger seat assemblies not installed)	No		
2015-10-51 07/01/2015	Navigation		Equipment not installed (affected Avidyne Integrated Flight Displays not installed)	No		
2015-16-04 09/15/2015	Fire Protection		Equipment not installed (affected Kidde Graviner hand-operated fire extinguishers not installed)	No		
2015-23-09 12/28/2015	Oxygen		Equipment not installed (affected Zodiac Aerotechnics oxygen mask regulators not installed)	No		
2017-04-06 04/07/2017	Cabin Systems		Equipment not installed (affected United Instruments 5934 series altimeters manufactured between Jan 2015 and Feb 2016 not installed)	No		
2017-06-03 05/05/2017	Heating System		Equipment not installed (affected Meggitt/Stewart Warner South Wind combustion heaters not installed)	No		
2017-09-09 06/28/2017	Passenger Compartment Equipment		Aircraft model and equipment not in applicability (applies to Zodiac Seats California LLC seating systems on certain transport category aircraft)	No		
2017-11-11 07/11/2017	ATC Transponder System		Equipment not installed (aircraft equipped with Garmin transponders, not NavWorx ADS600 series)	No		
2017-16-01 10/24/2017	Emergency Locator Beacon		Equipment not installed (aircraft equipped with Artex ME406 ELT, not Ameri-King AK-450/451)	No		
2017-18-12 10/16/2017	Oxygen		Equipment not installed (affected B/E Aerospace Protective Breathing Equipment not installed)	No		

Appliances (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Not Applicable (N/A) (continued)						
2017-22-14 12/20/2017	Navigation		Equipment not installed (Rockwell Collins TSS-4100 system / TSSA-4100 software not installed)	No		
2018-02-04 02/21/2018	Exhaust Noise Suppressor		Aircraft model and equipment not in applicability (applies to Aerospace Welding Minneapolis mufflers on Cessna 172/177 aircraft)	No		
2018-03-04 03/16/2018	Airspeed/Mach Indicator		Equipment not installed (Rosemount Model 851AK pitot probes repaired by CSI Aerospace not installed)	No		
2018-16-01 08/31/2018	Equipment		Equipment not installed (B/E Aerospace Fischer attendant/pilot seats not installed)	No		
2018-16-13 10/26/2018	Cabin Equipment/Furnishings		Equipment not installed (Zodiac Seats France 537-Series cabin attendant seats not installed)	No		
2018-17-11 09/24/2018	Fuel		Equipment not installed (Linstrandt T30 propane cylinders not installed; applies to hot air balloons)	No		
2018-19-15 11/14/2018	Cabin Equipment/Furnishings		Equipment not installed (GEVEN S.p.A. Type D1-02 and D1-03 seats not installed)	No		
2018-23-01 12/28/2018	Cabin Equipment/Furnishings		Equipment not installed (Zodiac Seats France 536-Series cabin attendant seats not installed)	No		
2018-23-12 12/28/2018	Equipment/furnishings		Equipment not installed; applies to Zodiac Aero Evacuation Systems fusible plugs on emergency evacuation equipment (not installed on Beechcraft 95-B55)	No		
2019-01-02 02/07/2019	Attitude and Direction Data System		Equipment not installed; applies to Aspen Avionics Evolution Flight Display units (aircraft is equipped with Garmin flight displays)	No		
2019-07-03 05/16/2019	Cabin Equipment/Furnishings		Equipment not installed; applies to Zodiac Seats France 536-series cabin attendant seats (not installed on Beechcraft 95-B55)	No		
2019-07-10 05/29/2019	Attitude and Directional Data System		Equipment not installed; applies to Northrop Grumman LITEF LCR-100 AHRS units (aircraft is equipped with Garmin GRS-77 AHRS)	No		
2019-08-01 05/21/2019	Passenger Compartment Equipment		Equipment not installed; applies to RECARO Model 3510A and 3510D passenger seats (not installed on Beechcraft 95-B55)	No		

Appliances (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Not Applicable (N/A) (continued)						
2019-13-03 08/27/2019	ATC transponder system		Equipment not installed; applies to Trig TT31, Avidyne AXP340, and BendixKing KT74 transponders (aircraft is equipped with Garmin GTX 345 transponder)	No		
2019-14-05 09/03/2019	Flight Compartment Equipment		Equipment not installed (applies to B/E Aerospace Fischer Common Seats 170/260 H160)	No		
2019-15-10 09/19/2019	Life Jacket		Equipment not installed (applies to Safran Aerosystems life jackets P/N 210225-2, 216200-0, or 216203-0)	No		
2019-21-09 12/18/2019	Life Jacket		Equipment not installed (applies to Aviointeriors Centaurus seats with life vest pouch P/N 313907100004)	No		
2020-08-02 05/19/2020	Global Positioning System		Equipment not installed (applies to Thales Topstar 200 LPV GPS/SBAS receivers P/N C17149JA02 and C17149HA01)	No		
2020-09-02 05/29/2020	Cabin Equipment/Furnishings		Equipment not installed (applies to Anjou Aeronautique Model 358 torso restraint systems)	No		
2020-10-05 06/24/2020	Flight Management Computing Hardware System		Equipment not installed (applies to Rockwell Collins Pro Line 4 and Pro Line 21 Flight Management Systems)	No		
2020-16-08 08/17/2020	Flight Environment Data, Attitude and Direction Data System		Aspen EFD1000 flight display not installed	No		
2020-18-51 09/28/2020	Attitude and Direction Data System		Sandia attitude indicator P/N 306171-10 or 306171-20 not installed	No		
2020-19-06 11/03/2020	Propellers		McCauley propeller governor not installed (aircraft equipped with Woodward governors)	No		
2020-21-02 11/19/2020	Fire protection		Kidde Aerospace cargo fire extinguisher halon bottle not installed	No		
2021-05-17 04/29/2021	NAVIGATION SYSTEM		Rockwell Collins FDSA-6500 flight display system application not installed	No		
2021-08-07 05/12/2021	NAVIGATION SYSTEM		Rockwell Collins GPS-4000S GPS P/N 822-2189-100 not installed	No		

Appliances (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Not Applicable (N/A) (continued)						
2021-22-07 11/18/2021	Fire Bottle, Portable		Equipment not installed; applies to Umlaut Engineering GmbH HAFEX fire extinguishers P/Ns P3APP003010A, P3APP003010B, and P3APP003010C on listed aircraft models	No		
2022-01-03 03/07/2022	Fire Bottle, Portable		Equipment not installed; applies to Umlaut Engineering GmbH HAFEX fire extinguishers P/Ns P3APP003010A and P3APP003010C manufactured March through July 2019	No		
2022-01-06 01/18/2022	Aircraft Fuel System		Aircraft category and equipment not installed; applies to hot air balloons equipped with Cameron Balloons Ltd. fuel cylinders fitted with flange adapter P/N CB437	No		
2022-03-15 03/21/2022	Fuel Quantity Indicator		Equipment and STC not installed; applies to airplanes modified with Garmin G3X Touch under STC SA01899WI or GI 275 MFD under STC SA02658SE interfaced with GEA 24	No		
2022-05-10 04/20/2022	Cabin Equipment/Furnishings		Aircraft category and equipment not installed; applies to helicopters equipped with an externally-mounted Goodrich hoist assembly	No		
2022-15-02 08/25/2022	Powerplant System		Aircraft category and equipment not installed; applies to hot air balloons equipped with Cameron Balloons Ltd. Stratus double burner assembly P/N CB8720 or P/N CB8721	No		
2023-10-02 05/26/2023	Indicating/Recording System, Navigation		Aircraft category (applies to transport and commuter category airplanes; Beechcraft 95-B55 is normal category) and equipment not installed	No		
2023-12-25 08/23/2023	Equipment/Furnishings		Equipment not installed (applies to specific Survitec Group Limited life jackets)	No		
2023-14-10 09/07/2023	Flight Compartment Equipment		Equipment not installed (applies to specific Ipeco pilot and co-pilot seats)	No		
2023-21-05 12/12/2023	Navigation System		Equipment not installed (applies to Thales FMC2 NAVM part number C13084CA03)	No		

Appliances (continued)

AD NO. & EFFECTIVE	DESCRIPTION	COMPLIED	METHOD OF COMPLIANCE / REASON	RECUR ?	NEXT DUE	CERT NO./TYPE, SIGNED
Not Applicable (N/A) (continued)						
2024-19-15 11/26/2024	Oxygen		Equipment not installed (applies to specific Safran Aerosystems/AVOX oxygen cylinder and valve assemblies)	No		
2024-20-04 11/12/2024	Flight Compartment Equipment		Aircraft category (applies to helicopters) and equipment not installed	No		
2025-07-01 05/15/2025	Air Data Computer		Equipment not installed (Thommen AC32 Digital Air Data Computer not installed; aircraft equipped with Garmin GDC 74A ADC)			
2025-12-02 06/30/2025	Equipment/furnishings		Equipment not installed (Ipeco pilot and co-pilot seats series 3A063 not installed)			
2025-21-01 10/27/2025	Aircraft Fuel System		Aircraft category / equipment not installed (applies to hot air balloons with Cameron Balloons PRV adaptor P/N CB8426)			
2026-08-10 05/11/2026	Passenger compartment equipment		Equipment not installed	No		
2026-10-05 07/06/2026	Equipment/furnishings		Make/model: DRS lists only other aircraft, engines or propellers (Goodrich; Airbus SAS), not this aircraft's 95-B55, IO-470-L, 3AF32C504-C			
2026-13-02 07/01/2026	Navigation		Applies to transport and commuter category aircraft	No		

Logbook ADs Not in FAA DRS

No ADs found for this component.

⚠ **Aviation AI Disclaimer.** Artificial Intelligence (AI) systems are not recognized as authoritative sources for airworthiness determinations. AI-generated information may contain errors, omissions, or inaccuracies. While AI tools may assist in data interpretation or documentation review, no airworthiness decision, inspection finding, or maintenance release shall be based solely on AI-generated output. All determinations affecting aircraft airworthiness must be verified through approved data, official manufacturer publications, and applicable FAA regulations or guidance material.